

Snorkel 2.0



Sold by Anaconda Stores between 02/09/2019 and 04/10/2019

Defect The snorkel may become blocked by the silicone washer designed to prevent water flowing into the snorkel when submerged. This may result in airflow being unexpectedly restricted and prevent the user from breathing normally when underwater.

Hazard If airflow is unexpectedly restricted, this increases the risk of drowning.

What to do Consumers should immediately stop using the product and return it to an Anaconda Store for a full refund of the purchase price.

Contact details For further information, consumers can contact Anaconda on 1300 558 990 or visit www.anacondastores.com/contact-us

See productsafety.gov.au for Australian product recall information